

FIG. 1




FIG. 2




FIG. 3




FIG. 4

Bulk Resistivity vs. Plasticizer Concentration




FIG. 5

